VESSEL SANITATION INSPECTION REPORT CORRECTIVE ACTION REPORT m/s RHAPSODY OF THE SEAS

Inspection Date: May 27th, 2001 Port of Inspection: Juneau Score: 99

DETAILS OF INSPECTION VIOLATIONS					
NO.	LOCATION	REF.	POINTS	CRITICAL	DESCRIPTION
1	WINDJAMMER BUFFET	33	0	NO	The deck junctures were not adequately coved CORRECTIVE ACTION: A solution is being worked in conjunction with the refurbishing department in the Miami office.
2	CHILD ACTIVITY CENTER	41	0	NO	There was no child size toilet located within the center. CORRECTIVE ACTION: It is being looked into finding the vendor that can provide with the adequate child size toilet.
3	SPA	10	0	NO	There was no sign installed near the whirlpool spas that lists standard safety precautions and risks, warning against use by particularly susceptible people such as those who are immunocompromised. CORRECTIVE ACTION: Awaiting new signs from the Miami office as this kind of sign needs to be standardized throughout the fleet.
4	GENERAL-OVERALL	*	0	NO	All items from the last inspection had been corrected. Overall operations and condition of the ship was excellent.
5	FOOD SERVICE - GENERAL	33	1	NO	Several deck tiles in various areas were cracked and contained missing recessed grouting. CORRECTIVE ACTION: Regrouting and repair of tiles in galleys is in progress.